


17. Main Terminal, Basement, South Hallway - General view of fireproofed concrete decking and structure above Ladies Rm




18. Main Terminal, Basement, South Hallway - View of delaminated fireproofing dust on top of fluorescent light fixture (location of dust sample #5)




19. Main Terminal, Basement, South Hallway - Close-up of delaminated fireproofing dust on top of fluorescent light fixture





20. Main Terminal, 3rd floor, Air Handler Room - General view of exposed fireproofed metal decking and beams



21. Main Terminal, 3rd floor, Air Handler Room - View of exposed fireproofed decking and beams above HVAC fan unit